



9. CONNECTION OF MOTOR CORD

CAUTION

- Before connecting to the Motor Cord to the Motor and CONTROLLER, verify the Main Power Switch in the CONTROLLER is turned OFF. If the Main Power Switch on the CONTROLLER is ON while connecting the Motor Cord, damage to the CONTROLLER is possible.
- Install the Protective Cap etc. to prevent damage or contamination to the Motor Cord Plug when not in use.

① Remove the Protective Cap of the Motor Cord.




Fig. 8

② Carefully insert the alignment pin into the alignment hole and push straight into the Connector of the Motor Cord.



Fig. 9

③ Tighten the Connector Nut with clockwise.



Fig. 10

④ Remove the protective air inlet Quick Disconnect Cover.



Fig. 11

⑤ Insert the provided air hose.




Fig. 12

10. INSTALLATION OF THE MOTOR SPINDLE

WARNING

When installing a Motor Spindle to a fixed base, make sure the fixed base is grounded in order to avoid the risk of an electric shock.

CAUTION

- When installing a Motor Spindle, do not hit, drop or cause shock to the Motor Spindle. This may cause damage to internal components and result in malfunctions.
- When mounting the Motor Spindle, be sure to secure within Clamping Area etched on the Motor Spindle O.D. If the Motor Spindle is installed incorrectly, damage to the internal components is possible.
- Cautions when tightening the securing bolts on a Split Type Holder  
Do not over-tighten the bolt. This will cause damage to Motor Spindle's precision.  
Tighten the bolt until the Motor Spindle body can not be rotated by hand within the fixture.  
Extreme tightening is not necessary or recommended.  
Apply working force and check that the Motor Spindle is tight before using.

① When mounting a Motor Spindle, refer to the Clamping Area etched on the Motor Spindle (Fig. 13).




Fig. 13

- When installing the Motor Spindle, it is recommended to use a "GR - 30 Grip Ring (sold separately (Fig. 14))". If the GR - 30 Grip Ring cannot be used due to the restriction of dimension and space, install as shown in ② below.




Fig. 14

② When installing a Motor Spindle to the holder, recommended installation method is shown Fig. 15. Refer to ③

How to fabricate the Split Type Holder \*  
If this is not possible, install as shown in Fig. 16.



Fig. 15




Fig. 16

Fig. 17

CAUTION

Do not allow set screws to come directly in contact with the Motor Spindle body as shown in Fig. 17, as this will result in damage to the Motor Spindle housing and internal components.  
When installing, never clamp directly over the bearings, as this will result in bearing damage (Refer to Fig. 18).




Fig. 18

① How to fabricate the Split Type Holder

- (1) Rough bore the inside diameter of the Split Type Holder.
- (2) Cut a slit, (Ex. Slit 2mm) wide.
- (3) Tighten the Screw for Removal and Force Open the Slit Area.
- (4) Insert a spacer, (Ex. thickness = 2mm) into the Slit Area.
- (5) Loosen the Screw for Removal, and tighten the fastening bolt with its specified torque.
- (6) Finish the Split Type Holder so that the inside diameter of the Split Type Holder is  $\phi 30$  with its tolerance range from  $-0.01$  mm to  $-0.015$  mm, and its roundness and cylindricity of less than  $5\mu$ m.
- (7) When inserting the Motor Spindle, loosen the Fastening Bolt, and tighten the Screw for Removal, widening the Slit Area.




Fig. 19

Front View

Side View

CAUTION

- How to confirm the correct tightening or clamping of the Motor Spindles in the holder  
Measure the current value of the CONTROLLER's power cord by the clamp meter.  
Fasten the holder so that the increase in the no-load current value (during rotation at the maximum rotation speed) with the Motor Spindle fastened is 20mA (for type 120V) / 10mA (for type 200V / 230V) or less, compared to the no-load current value (during rotation at the maximum rotation speed) without fastening the Motor Spindle. Do not over-tighten the Fastening Bolt. It may damage Motor Spindle's precision and shorten the life of the bearings.  
• The final responsibility for ensuring holder's safety for use in a given application is left to the designer of the equipment in which NAKANISHI's Motor Spindle is installed.  
NAKANISHI offers Motor Spindles with a wide variety of capabilities and specifications.  
Please carefully check the Motor Spindle's specifications against the requirements of your equipment and verify suitability and safety of the Holder prior to initial use.

11. BREAK-IN PROCEDURE

During transportation, storage or installation, the grease inside the bearings will settle. If the spindle is suddenly run at high-speed, the grease will be ejected from the bearings, causing excessive heat that will cause bearing damage. After installation, repair, initial operation, or long periods of non operation, please follow the break-in procedure detailed in Table 2.

Table 2

| Steps                                                       | 1                   | 2                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 3                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 4                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 5                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|-------------------------------------------------------------|---------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Rotation Speed (mm <sup>3</sup> / (mm <sup>3</sup> )) (rpm) | 15,000              | 30,000                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 40,000                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 50,000                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 60,000                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| Rotation Time (min)                                         | 15                  | 10                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 10                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 10                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 10                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| Items to Check                                              | No Abnormal Noises. | The Motor Spindle housing temperature during the break-in process should not exceed 20 degrees C (36 degrees F) above ambient temperature. Should the Motor Spindle exceed this limit, rest the Motor Spindle for at least 20 minutes and re-start the break in procedure from the beginning. If the housing temperature rises again and exceeds 20 degrees C (36 degrees F) above ambient temperature, check the Motor Spindle for proper installation. | The Motor Spindle housing temperature during the break-in process should not exceed 20 degrees C (36 degrees F) above ambient temperature. Should the Motor Spindle exceed this limit, rest the Motor Spindle for at least 20 minutes and re-start the break in procedure from the beginning. If the housing temperature rises again and exceeds 20 degrees C (36 degrees F) above ambient temperature, check the Motor Spindle for proper installation. | The Motor Spindle housing temperature during the break-in process should not exceed 20 degrees C (36 degrees F) above ambient temperature. Should the Motor Spindle exceed this limit, rest the Motor Spindle for at least 20 minutes and re-start the break in procedure from the beginning. If the housing temperature rises again and exceeds 20 degrees C (36 degrees F) above ambient temperature, check the Motor Spindle for proper installation. | The Motor Spindle housing temperature during the break-in process should not exceed 20 degrees C (36 degrees F) above ambient temperature. Should the Motor Spindle exceed this limit, rest the Motor Spindle for at least 20 minutes and re-start the break in procedure from the beginning. If the housing temperature rises again and exceeds 20 degrees C (36 degrees F) above ambient temperature, check the Motor Spindle for proper installation. |

12. CAUTIONS WHEN USING GRINDSTONES AND TOOLS

CAUTION

The maximum surface speed or rpm is always specified for a grindstone. Do not exceed the maximum speed with reference to the calculating chart below. Always follow the grindstone manufacturer's recommendations.

$$\text{Surface Speed (m/s)} = \frac{3.14 \times \text{Diameter (mm)} \times \text{Rotation Speed (min}^{-1}\text{)} (\text{rpm})}{1,000 \times 60}$$

- ① The proper surface speed for general grindstones is 10 - 30m / s.
- ② Do not exceed 13mm of overhang for mounted grindstones as shown in Fig. 20. If the overhang must exceed 13mm, reduce the motor speed in accordance with Table 3.
- ③ Dress the grindstone prior to use.
- ④ Do not use cutting tools with bent or broken shanks, cracks or excessive run-out.
- ⑤ For grinding, the maximum depth of cut should not exceed 0.01mm radially or axially. Reciprocate the tool several times after each pass to eliminate tool pressure.
- ⑥ Always operate cutting tools within the allowable recommended speed of the cutting tools. Use of a cutting tool outside of the allowable speed of the cutting tools could cause damage to the spindle and injury to the operator.
- ⑦ Keep the cutting tool shank and collet chuck clean. If contaminants are left in the collet chuck or chuck nut, excessive run-out will cause damage to the cutting tool and or spindle.
- ⑧ Do not strike or disassemble the spindle.
- ⑨ Please set the cutting tools to minimize the overhang amount. 13mm is the maximum amount of overhang to maintain high accuracy and safety.

Table 3 Overhang and Speed

| Overhang (mm) | Max. Speed (min <sup>-1</sup> ) (rpm) |
|---------------|---------------------------------------|
| 20            | N x 0.5                               |
| 25            | N x 0.3                               |
| 50            | N x 0.1                               |

\* N = Max. Operating Speed with 13mm overhang.




Fig. 20

13. TROUBLESHOOTING

If a problem or concern occur, please check the following items prior to consulting your dealer.

| Trouble                                           | Cause                                                                                                                                                                                                                                                                        | Inspection / Corrective Action                                                                                                                                                                                           |
|---------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Motor Spindle does not rotate or rotate smoothly. | The Motor Spindle ball bearings have been damaged.<br>The motor has been damaged.                                                                                                                                                                                            | Replace the ball bearings.<br>(Return to NAKANISHI dealer service.)<br>Replace the motor.<br>(Return to NAKANISHI dealer service.)                                                                                       |
| Overheating during rotation.                      | Cutting debris has contaminated the ball bearings, and the ball bearings are damaged.<br>Low air pressure.                                                                                                                                                                   | Replace the ball bearings.<br>(Return to NAKANISHI dealer service.)<br>Check air hose connection and air pressure.<br>Replace the tool.                                                                                  |
| Abnormal vibration or noise during rotation.      | The tool shank is bent.<br>Cutting debris has contaminated the ball bearing.<br>The Motor Spindle ball bearings have been damaged.                                                                                                                                           | Replace the ball bearings.<br>(Return to NAKANISHI dealer service.)<br>Check and clean the collet chuck and chuck nut. Reinstall the collet chuck and chuck nut.<br>Replace the collet chuck and chuck nut.              |
| Tool allpage.                                     | Collet chuck or chuck nut are not correctly installed.<br>The collet chuck and the chuck nut are worn.                                                                                                                                                                       | Change the tool.<br>Secure the collet chuck and the chuck nut correctly.<br>Replace the collet chuck and the chuck nut.                                                                                                  |
| High run-out.                                     | The tool is bent.<br>Chuck nut is not correctly installed.<br>The collet chuck and the chuck nut are worn.<br>Inside of the spindle is worn.<br>Contaminants inside the collet chuck and the chuck nut or the spindle.<br>The Motor Spindle ball bearings have been damaged. | Replace the spindle shaft.<br>(Return to NAKANISHI dealer service.)<br>Clean the collet chuck, chuck nut and the inside of the lager and spindle.<br>Replace the ball bearings.<br>(Return to NAKANISHI dealer service.) |

Refer to the E3000 CONTROLLER Operation Manual.

14. DISPOSAL OF THE MOTOR SPINDLE

When disposal of a Motor Spindle is necessary, follow the instructions from your local government agency for proper disposal of industrial components.

NAKANISHI INC. ■  
1-1-1, Nishikuwa, Nishikuwa-cho, Nishikuwa-shi, Tokyo 162-8666, Japan  
www.nakanishi-inc.com

NSK America Corp.  
10000 W. Century Blvd., Suite 100, Dallas, TX 75243, USA  
www.nskamericacorp.com

NSK Europe GmbH (GmbH)  
Postfach 10 15 50, D-42699 Solingen, Germany  
www.nsk-europe.com

NSK United Kingdom Ltd.  
Office 4, Gateway 1000  
Arlington Business Park, White Way  
Surrey, Surrey, UK GU1 1PT, UK